







ASSEMBLY INSTRUCTIONS:

1. PREPARE CABLE ENDS. CONNECT TO CONNECTOR
2. IF THE JACKSCREWS ARE NOT IN PLACE, DO NOT PUSH THEM IN, SCREW THEM INTO THE CONNECTOR
3. SELECT THE CABLE ENTRY PORT NEEDED, PLACE THE SLOT BLOCKING TABS IN THE OTHER TWO POSITIONS MAKING SURE THEY ARE FULLY SEATED
4. PLACE CABLE IN SELECTED STRAIN RELIEF RECESS AREA MAKING SURE CABLE JACKET IS BELOW STRAIN RELIEF. ENSURE THE CABLE IS PRESSED INTO THE STRAIN RELIEF RECESS AREA
5. PLACE CABLE CLAMP OVER CABLE. USING SCREWS PROVIDED, TIGHTEN CABLE CLAMP. CABLE CLAMP MAY BE INSTALLED UP SIDE DOWN FOR SMALLER CABLES
6. PLACE THE OTHER HALVE OF THE HOOD ON TOP OF THE FIRST HALF, MAKING SURE NO WIRES ARE PINCHED
7. TIGHTEN THE TWO HALVES TOGETHER WITH THE SCREWS PROVIDED



ROHS COMPLIANT

PLASTIC

NC
THESE DRAWINGS AND SPECIFICATIONS ARE THE PROPERTY OF NorComp AND SHALL NOT BE REPRODUCED, COPIED OR USED AS THE BASIS FOR THE MANUFACTURE OF SALE OF APPARATUS, WITHOUT WRITTEN PERMISSION.

DRAWN:	C. SMITH	DATE:	03-27-06
CHECKED:	X	DATE:	X

SCALE:	N.T.S.	SHEET	1	OF	2	REV	0
--------	--------	-------	---	----	---	-----	---

NorComp

DWG NO. BACKSHELL - 975 SERIES